

SIMODRIVE 660
AC Main Spindle Drive
Converters

Description

10.92 Edition

SIMODRIVE 660

Transistor PWM Converters

for

AC Main Spindle Drives

Description

SIMODRIVE® documentation

Printing history

Brief details of this edition are listed below.
The status of each edition is shown by the code in the 'Remarks' column.
Status code in the "Remarks" column:

- A . . .** New documentation.
- B . . .** Unrevised reprint with new Order No.
- C . . .** Revised edition with new status. If factual changes have been made since the last edition, this is indicated by a new edition coding in the header on that page.

Edition	Order No.	Remarks
10.92	6ZB5 420-0AQ02-0BA0	A

Other functions not described in this documentation might be executable in the control. This does not, however, represent an obligation to supply such functions with a new control or when servicing

This publication was produced on the Siemens 5800 Office system.
Subject to change without prior notice.

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design are reserved.

Preliminary information

This document is part of the SIMODRIVE® documentation. All documents can be obtained individually. Please contact your local Siemens office for a complete listing of all of the documentation including the advertising brochures, catalogs, overviews, product briefs, instruction manuals and reference manuals with Order No., where they can be ordered and price.


	WARNING
	The data and instructions in all of the instruction manuals and any other instructions must always be observed to prevent potentially dangerous situations and damage. • Additional safety information (yellow) is provided with the Instruction Manual, which includes supplementary information regarding safety measures for electrical machines and equipment. This safety information should also be used in conjunction with all other Manuals which are provided (e.g. for brakes, etc.). • For special machines and equipment, the specifications in the catalogs and quotations are valid. • Further, the relevant national, local and plant-specific regulations and specifications must be observed.



Please note that the color coding of the connecting cables can change, therefore please check the signal cables before you attach the connectors.



Warning information

	WARNING
	Hazardous voltages are present in this electrical equipment during operation. Non observance of the safety instructions can result in severe personal injury or property damage. Only qualified personnel should work on or around the equipment after first becoming thoroughly familiar with all warning and safety notices and maintenance procedures contained herein. The successful and safe operation of this equipment is dependent on proper handling, installation, operation and maintenance.

Definitions

• Qualified personnel

For the purpose of this Description and product labels, a ‘Qualified person’ is someone who is familiar with the installation, construction and operation of the equipment and the hazards involved. He or she must have the following qualifications:

1. Trained and authorized to energize, de-energize, clear, ground and tag circuits and equipment in accordance with established safety procedures.
2. Trained in the proper care and use of protective equipment in accordance with established safety procedures.
3. Trained in rendering first aid

• DANGER

For the purpose of this Description and product labels, ‘Danger’ indicates death, severe personal injury or substantial property damage will result if the proper precautions are not taken.

• WARNING

For the purpose of this Description and product labels, ‘Warning’ indicates death, severe personal injury or substantial property damage can result if proper precautions are not taken

• CAUTION

For the purpose of this Description and product labels, ‘Caution’ indicates minor personal injury or property damage can result if proper precautions are not taken.

• NOTE

For the purpose of this Description, ‘Note’ indicates information about the product or the respective part of the Description which is essential to highlight.

AC Main Spindle Drives

1

Transistor PWM Converters

2

Matching Transformers

3

Installation Instructions

4

Appendix

5

Contents

	Page
1 AC main spindle drives	1-1
1.1 Application	1-1
1.2 Mode of operation	1-5
1.3 Complete standard drives	1-6
2 Transistor PWM converters	2-1
2.1 Application	2-1
2.2 Design	2-1
2.3 Mode of operation	2-4
2.3.1 Power section	2-4
2.3.2 Closed-loop control	2-4
2.3.3 Software board	2-5
2.3.4 Special applications	2-5
2.3.4.1 "C-axis mode"	2-5
2.3.4.2 Motor encoder output	2-5
2.3.4.3 Master/slave drive	2-7
2.4 Options	2-10
2.4.1 "PG/PC coupling" option	2-10
2.4.2 "External heat dissipation" option	2-10
2.4.3 "Flange for connecting external heat dissipation" option	2-10
2.5 Start-up	2-11
2.6 Interfaces	2-12
2.6.1 Signal inputs	2-12
2.6.1.1 Analog signals	2-12
2.6.1.2 Binary signals	2-12
2.6.2. Signal outputs	2-15
2.6.2.1 Analog signals	2-15
2.6.2.2 Binary signals	2-16
2.6.2.3 Encoder signals	2-17
2.6.2.4 Display messages	2-17
2.7 Engineering information for dimensioning the DC link for a combination drive consisting of SIMODRIVE 660 and SIMODRIVE 611	2-18
2.8 Technical data	2-19
2.9 Product designation	2-22
2.9.1 Converter	2-22
2.9.2 Software board	2-23
2.9.3 Start-up software for PG/PC	2-23
3 Matching transformers	3-1
3.1 Application	3-1
3.2 Technical data of the autotransformers	3-1

4	Installation instructions	4-1
4.1	PWM converters	4-1
4.1.1	Mounting the PWM converter	4-1
4.1.2	Connecting-up the PWM converter	4-1
4.1.3	Board handling	4-4
4.1.4	PWM converter terminals	4-5
4.1.5	Recommended connection	4-9
4.2	Cable connections	4-11
5	Appendix	5-1
5.1	Dimension drawings, PWM convertersr	5-1
5.2	Dimension drawing, autotransformer	5-9


1 AC main spindle drives

1.1 Application

The SIMODRIVE® AC main spindle drives for machine tools described here, consist of a matched combination of 1PH AC squirrel-cage induction motors with sine/cosine encoder system and SIMODRIVE 660 transistor PWM converters.

SIMODRIVE main spindle drives combine the advantages of induction motors - rugged and low-maintenance - with state-of-the-art microprocessor technology. Using the TRANSVEKTOR® closed-loop control developed by Siemens, it has become possible to control induction motors with a control performance comparable to that of DC drives. Digital technology allows extremely short start-up times by presetting the main spindle drive, as well as a comprehensive measuring and diagnostics system. With these characteristics, SIMODRIVE AC main spindle drives fulfill all the requirements demanded of a drive concept for machine tools in modern production facilities:

- Fast start-up
- High degree of operator friendliness and simple diagnostics
- High operational reliability
- Very low maintenance
- Simple reproducibility of settings, e.g. during servicing
- Wide speed range at constant power
- Reduction of the number of mechanical gear stages




1PH AC motors and SIMODRIVE 660 transistor PWM converter

Detailed information on the motors is included in the description of the AC main spindle motors.


Important characteristics of transistor PWM converters

- They can be directly connected to the supply without transformer, commutating reactors and inrush current limiting
- Regenerative feedback into the line supply during braking
- Digital microprocessor concept
- High long-time accuracy of the control parameters
- Load and control characteristics similar to a DC motor as a result of field-oriented closed-loop control
- C axis as standard
- Simple and fast digital parameter input
- Operating and fault message displays
- High degree of safety and reliability using monitoring circuits
- Microprocessor-based diagnostics
- Options:
 - Spindle positioning
 - Fast start-up with a programming unit (PG)/PC-AT


SIMODRIVE 660 PWM converter and 1PH motors with rated outputs up to 76 kW at rated speeds from 500 to 2000 RPM



SIMODRIVE 660 PWM converter and 1PH motors using programming units and PCs for start-up and diagnostics:




SIMODRIVE 660 PWM converter, spindle positioning option (without NC):




Applications of the SIMODRIVE 660 transistor PWM converter

Main spindle drive with SIMODRIVE 660 and 1PH motors as twin drive for coupled axes:



SIMODRIVE 660 main spindle drive with 1PH motors and SIMODRIVE 611 feed drive with 1FT5 motors




Applications of the SIMODRIVE 660 transistor PWM converter

1.2 Mode of operation

With SIMODRIVE AC main spindle drives, the TRANSVEKTOR® closed-loop control concept has been introduced in the machine tool sector, which is based on the principle of field-oriented closed-loop control. In conjunction with FCS (Frequency Compensated Spindle drive) closed-loop control, a high-performance current control technique, it is possible to operate induction motors with a dynamic performance and precision which has been almost unknown up until the present time. The advantages of digital technology (accuracy) and analog technology (speed) are ideally combined. The open- and closed-loop control of the AC main spindle drive consists of a closed-loop speed controller with ramp-function generator and stored field weakening characteristic, a secondary closed-loop current control circuit, inverter control system and sequential logic.

While AC drives used up until now always represented a non-linear controlled system, here, for the first time, a linear relationship exists, where the induction motor behaves similar to a DC motor and where the armature current (with constant excitation) is proportional to the torque.



Block diagram of the SIMODRIVE AC main spindle drive

It is possible to rapidly change the stator voltage and frequency of the AC motor using the transistor PWM converter.

The decoupling of these two motor variables is simulated in a microprocessor computer module. The reference variables for the motor supply, frequency, phase position and amplitude are generated using this computer model to provide each required torque and magnetic field, taking into account the torque and field limits. The resulting stator current vector comprises rotor flux and torque-generating current components to the rotor flux. Field-oriented operation exists if the current components generating the flux remain constant and the current components generating torque are established vertically to the rotor flux corresponding to the required torque.

The ability to generate the current vector oriented to the flux vector phase position (field orientation) allows torque and flux to be separately controlled, and permits a control quality to be achieved which is better than DC technology.

The sequential logic in addition to the field-oriented control, is also realized in the microprocessor.

Digital technology provides a high degree of user-friendliness and a high level of reproducibility of the setting variables. The parameters required for the closed-loop control are stored in a non-volatile EEPROM, and can also transferred into other PWM converters.

1.3 Complete standard drives

The standard drives available are listed in the table. An appropriate PWM converter is assigned to each AC motor depending on the required overload capability. The available overload capability refers to S6 duty with a load cycle duration of 10 minutes. Please refer to the specific speed-power diagrams of the motors for the permissible speed control range as well as the permissible switch-on duration with overload (AC main spindle motor description).

Contrary to DC technology, there is no linear relationship between current and torque of AC motors as a result of the magnetizing current. Thus, the currents necessary for the demanded overload capability of a specific AC motor are already taken into account for the required PWM converter in the subsequent tables.

PWM converter thermal time constants are significantly lower than those for AC motors. The converters are thermally dimensioned for continuous operation. Further, the 6SC6612 and 6SC6620 converters have an overload capability. These characteristics are taken into account in the following table. The switch-on duration for S6 duty should be taken from the motor data sheets.

SIMODRIVE 611 main spindle modules can be used to feed motors having lower outputs. The applicable assignment table is included in the Description, SIMODRIVE 611 main spindle modules.

2 Transistor PWM converters

2.1 Application

SIMODRIVE 660 transistor PWM converters have been developed to supply 1PH AC main spindle motors equipped with sine/cosine encoder systems, with a controlled 600 V DC link voltage and fully regenerative braking. They control the drive power and speed of the drive in 4-quadrant operation. Three converters with rated apparent outputs from between 60 and 150 kVA are available.

The transistor PWM converters are mounted in an enclosure together with the incoming fuses and can be directly connected to a three-phase 400 V AC 50/60 Hz supply. Transformers, commutating reactors and inrush limiters are not required. Monitoring electronics provides short-circuit-, overload-, and ground fault protection for the converters. The TRANSVEKTOR® closed-loop control concept guarantees high control performance such as is required for C-axis operation.

All 1PH motor data required for calculating the field is stored in a converter memory. During start-up, the microprocessor automatically provides the complete motor data. Customer-specific closed-loop control parameters can be entered or changed on a display and operator control unit. During operation, operational statuses and faults are indicated on the 6-digit display of the display and operator control unit.

All parameters and fault messages can be displayed in plain text on the PG/PC with the interface for connecting programming units or PCs. A data set can be stored on floppy disk and can be used for other standard machines.


2.2 Design

The power section consists of


- A line-side converter with regenerative feedback into the supply:
- A DC voltage link and
- A transistor PWM converter which generates a variable-voltage and variable-frequency three-phase system

The electronics is supplied from the DC link, thus providing ride-through capability during brief supply voltage failures.


The necessary line-side fuses are incorporated in the PWM converter. Fuses are not blown when the supply voltage fails when the unit is in the regenerative mode.



Design of the 6SC6608 transistor PWM inverter



Design of the 6SC6612 transistor PWM inverter




Design of the 6SC6620 transistor PWM inverter

- N2 = Infeed/regenerative feedback board
- S1 = Option
- G1 = Central controller board
- a = X114 = Relay outputs
- D1 = Software board (supplied separately)
- A1 = Gating board/power section
- N1 = Control board
- b = X112 = Serial interface
- c = X113 = Motor encoder output
- d = X114 = Motor encoder input
- e = X121:A = Speed setpoints
- f = X121:B = D/A converter outputs
- g = X122:A = Terminals (permanently assigned)
- h = X122:B = Terminals (freely programmable)


2.3.4.3 Master/slave drive

Two SIMODRIVE main spindle drives can be operated when they are rigidly mechanically coupled if the master drive is speed controlled and the slave drive is torque controlled.



Block diagram of a coupled drive

- Rigid drive coupling



Wiring of the gating logic for rigidly coupled drives

Master drive:	D/A 2:	Actual torque setpoint for open-loop torque control (address 0C6EH in P-068)
Slave drive:	Term. E5:	Open-loop torque control (4 in P-085)

The diagram illustrates the wiring of the gating logic for the configuration where the drives are never decoupled in operation. With this type of control, for all static and dynamic drive loads, the coupling must have a no-torque condition, i.e. the machines must never drive each other.


If two different machines are used, or with different gearbox ratios, the motors should not be operated dynamically at the torque limit. Speed changes should only be realized via the master drive setpoint channel.

The drives coast down when the pulses are inhibited.

The ramp-function generator (parameters P-016 and P-017) must be set, so that the drives never reach torque limiting during dynamic operation.

Separate control relays should be used for the master and slave drives (e.g. both terminals 63 should not be switched with 1 contact), so that both 24 V power supplies of the drives remain isolated with respect to each other.

- **Quasi-rigid drive coupling**



Master drive:	D/A 3:	Actual speed setpoint for open-loop torque control (address 304CH in P-076)
Slave drive:	Terminal E5:	Open-loop torque control (4 in P-085)

The diagram shows the control logic wiring for the application where both drives can be operated decoupled, e.g. if the motors are coupled through a workpiece. In this case, the drives must be able to be operated coupled and also separately, in which case both drives require their own speed control.

Relay D7 switches the slave drive from closed-loop speed control to closed-loop torque control. This changeover must be interlocked so that it is only possible if it is guaranteed that both motors are mechanically coupled (checkback signal).

The "separate closed-loop speed control" mode must only be possible if the motors are not coupled. This mode must be selected via terminal 64, i.e. the speed setpoint must be switched to both drives, and the drive which should not run, does not receive a controller enable signal.

2.6.2.3 Encoder signals

The motor encoder signals are provided as a square-wave pulses at connector X113 of the control board for external use. This output is fed through a driver stage in the PWM converter so that it is decoupled from the control.

An adapter cable is available for this connection.


2.6.2.4 Display messages

Measured values, operating displays or fault messages are alternatively displayed on the six-digit display.

- **Operating displays:**
 - PWM converter ready
 - Enable status
 - Control type
 - Torque direction
 - Gearbox stage
 - Status of the digital inputs
 - Status of the digital outputs
- **Measured values:**
 - n_{set}
 - n_{act}
 - P/P_{max} in %
 - M/M_{max} in %
 - Motor temperature
 - Active terminal functions
- **Fault messages:**
(several simultaneous faults can be called-up one after another)
 - Supply fault
 - Incorrect phase sequence
 - Defective encoder system
 - Speed controller at its limit, speed actual value missing
 - Motor overtemperature
 - Converter overtemperature
 - Incorrect motor/converter assignment
 - Temperature sensor
 - interrupted
 - short-circuited
 - Internal power supply faulted
 - DC link overvoltage
 - DC link overcurrent
 - DC link charge fault
 - Supply synchronizing error

2.8 Technical data

Supply voltage	3-ph. AC 400 V (–10%/ + 6%)
Rated frequency	50/60 Hz
Output voltage	3-ph. AC 0 to 430 V
Output frequency	0 to 600 Hz
Efficiency at rated operation	approx. 95%
DC link voltage	600 V DC
Pulse frequency	2.5/3.3 kHz ¹⁾ can be parameterized
Permissible ambient temperature in operation during transport and storage	0 °C to 40 °C (with derating up to 55 °C) –25 °C to 85 °C




Insulation	DIN VDE 0160 for application locations according to DIN VDE 0110, insulation group C
High-voltage test	Converters are tested according to VDE 0160/5.88
Degree of protection	IP 00 according to DIN 40050 and IEC 144
Permissible humidity rating	Class F according to DIN 40040 Annual average relative humidity ≤ 75 % 30 days annually, continuous 95 % on the other days, occasionally 85 %
Cooling type	Forced cooled Cooling air flow: 6SC6608 approx. 230 m ³ /h 6SC6612 approx. 300 m ³ /h 6SC6620 approx. 450 m ³ /h

1) Derating at 3.3 kHz

Installation altitude


The specified load values are referred to installation altitudes up to 1000 m above sea level. For installation altitudes above 1000 m, the load values should be reduced according to the diagram below.



PWM converter	Current drawn from the supply		Output current	Appar-ent output power	Contin-uous infeed power	Contin-uous regen-erative power	Max. power loss	Input fuses (incorp-orated)	Weight approx.
	at rated voltage [A]	at under-voltage [A]							
Order No.			[A]					[A]	[kg]
08-□	72	82	85	60	56	45	1500	125	70
12-□	108	123	120 ¹⁾	90	87	70	2300	200	90
20-□	180	205	200 ²⁾	150	120	100	3600	315	225

Technical data of the PWM converter

1) S6-60% (10 min cycle) 140 A, S6-40 % (10 min cycle) 150 A
2) S6-60% 250 A



Max. power loss at rated voltage as a function of the output current and with power loss dissipation, option E45 (external heat dissipation).

(The difference between the two converter characteristics corresponds to the heat which is not dissipated)


2.9 Product designation

The product designation (which is also the Order No.) consists of a combination of digits and letters.

The first block consists of seven positions and designates the PWM converter type, or for accessories, the allocation to a product family. Additional features are coded in the second block.


2.9.1 Converter

Order No. structure:



2.9.2 Software board

Order No. structure:



Software board (programmed)


Version

00 = Actual software release

XY = Software release XY

2.9.3 Start-up software for PG/PC

Order No. Structure:



Floppy disk size

B = 5 1/4" floppy disk

C = 3 1/2" floppy disk

Release

00 = Current release

XX = Release XX

Licensing type

0 = Individual license

3 = Master license, 10 uses

4 = Master license, 20 uses

5 = Master license, 50 uses

6 = Master license, 100 uses


7 = Master license, 200 uses

4.1.3 Board handling


Please observe the following information:

- Electronic boards should only be touched if absolutely necessary.
- The human body must be electrically discharged before touching an electronic board. This is simply done by touching a conductive, grounded object immediately beforehand (e.g. bare metal cubicle components, socket protective conductor contact).
- Boards must not come into contact with highly-insulating materials (e.g. plastic foils, insulating desktops, articles of clothing manufactured from man-made fibers).
- Boards must only be placed on conductive surfaces.
- Boards can only be inserted or withdrawn under a no-voltage condition.
- Signal voltages can only be connected to the boards when the supply voltage is switched-on.
- Boards and components should always be stored or transported in conductive packaging (e.g. metalized plastic containers, metal boxes).
- If the packaging is conductive, the boards must be wrapped in conductive materials before packing. For example, conductive foam rubber or household aluminum foil can be used.

Position of the converter connections




Position of the connectors. 6SC6608 transistor PWM converter




Position of the connectors. 6SC6612 transistor PWM converter


4.1.4 PWM converter connecting terminals



Position of the connectors, 6SC6620 transistor PWM converter

- N2 = Infeed/regenerative feedback board
- S1 = Option
- G1 = Central board
- a = X114 = Relay outputs
- D1 = Software board
- A1 = Gating board/power section
- N1 = Control board
- b = X112 = Serial interface
- c = X113 = Motor encoder output
- d = X114 = Motor encoder input
- e = X121:A = Speed setpoints
- f = X121:B = D/A converter outputs
- g = X122:A = Terminals (permanently assigned)
- h = X122:B = Terminals (freely-programmable)





Dimension drawing 'external heat dissipation, connecting flange' option (6SC6612)

<

Siemens AG
Automation Group
Automation Systems
for Machine Tools, Robots
and Special-Purpose Machines
P.O. Box 48 48, W-8500 Nuremberg 1
Federal Republic of Germany

Siemens Aktiengesellschaft

© Siemens AG 1992 All Rights Reserved
Subject to change without prior notice

Order No.: 6ZB5 420-0AQ02-0BA0
Printed in the Fed. Rep. of Germany
252/07796 BS 02930.3



Progress
in Automation.
Siemens