

MiCS-5914 with recommended supply circuit (top view)


R1 is typically a E96 resistor at 93.1  $\Omega$ . This resistor is necessary to obtain the right temperature on the heater while using a single 5V power supply. The resulting voltage is typically VH = 2.2V.


MiCS-5914 with measurement circuit (top view)

The voltage measured on the load resistor is directly linked to the resistance of the sensor respectively. RLOAD must be 820  $\Omega$  at the lowest in order not to damage the sensitive layer.

Parameter	Symbol	Тур	Min	Max	Unit
Heating power	P <sub>H</sub>	66	60	73	mW
Heating voltage	V <sub>H</sub>	2.2	-	-	V
Heating current	I <sub>H</sub>	30	-	-	mA
Heating resistance at nominal power	R <sub>H</sub>	72	64	80	Ω

Rating	Symbol	Value / Range	Unit
Maximum heater power dissipation	P <sub>H</sub>	88	mW
Maximum sensitive layer power dissipation	Ps	8	mW
Voltage supplyHeating current	Vsupply	4.9 – 5.1	V
Relative humidity range	RH	5 – 95	%RH
Ambient operating temperature	Tamb	-30 – 85	°C
Storage temperature range	Tsto	-40 – 120	°C
Storage humidity range	RHsto	5 - 95	%RH






## **Package outline dimensions**

The package is compatible with SMD assembly process.

Pin	Connection
A	
В	
С	Rh1
D	Rs1
Е	
F	Rh2
G	Rs2
Н	
J	
K	



MiCS-5914 configuration (bottom view)

## Sensor configuration

The silicon gas sensor structure consists of an accurately micro machined diaphragm with an embedded heating resistor and the sensing layer on top.

The internal connections are shown above.