


Dimensions

With Straight, Instant Connection, Decompression Valve




$\varnothing A =$  G 3/8  
(1) 2 tapped entries for Pg 13.5

---

Minimum Mounting Clearance

---



ØA = G 3/8  
(1) Minimum clearance zone for screwing-on pressure switch at point A